

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>110663</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/02/2025</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  
**ROBESON COUNTY DETENTION CENTER**

STREET ADDRESS, CITY, STATE, ZIP CODE  
**122 LEGEND ROAD  
LUMBERTON, NC 28358**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

J 00	<p>Initial Comments</p> <p>Charles Brown conducted the inspection.</p> <p>This biannual jail inspection was conducted as per 10A NCAC 14J JAILS, LOCAL CONFINEMENT FACILITIES Rules. This building was approved for use in 1992 under North Carolina State Building Code 1978 Edition with an occupancy classification of Group I-3. The jail design capacity is 354 male beds and 56 female beds with a total design capacity of 410 beds. The inspection began at 8:30 am and ended at 10:30 am. On the day of the inspection the weather was cool with rainy conditions. Robeson County Detention Center Major Howard was present and toured the facility with the inspector.</p> <p>The deficiencies determined during the inspection are as follows:</p>	J 00		
J 04	<p>10A NCAC 14J .0103 (b) Applicability-Construction</p> <p>(b) An existing jail I and II shall meet the requirements of the North Carolina State Building Codes in effect at the time of construction, addition, alteration, or repair.</p> <p>History Note: Authority G.S. 153A 221; Eff. June 1, 1990; Readopted Eff. September 4, 2020.</p> <p>This Rule is not met as evidenced by: Based on observation on 12/02/2025, the fire alarm system is not fully operational as required by the North Carolina Electrical Code and the National Fire Protection Association (NFPA) 72: National Fire Alarm Code.</p> <p>Findings include:</p>	J 04		

Division of Health Service Regulation  
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

*Major Ryan Abweval*

TITLE

*Jail Administrator*

(X6) DATE

*1-15-26*

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>110663</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/02/2025</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>ROBESON COUNTY DETENTION CENTER</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>122 LEGEND ROAD LUMBERTON, NC 28358</b>
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
J 04	Continued From page 1  There was trouble code displayed on the fire alarm control panel which should be repaired and returned to its normal operating status.	J 04	The Fire alarm has been returned to normal operating status.	12/8/25
J 21	<p>10A NCAC 14J .0301 (b) Classification System and Total Design Cap</p> <p>(b) When a jail exceeds its total design capacity, the sheriff, regional jail administrator, or their designees shall relocate inmates to another jail or prison to bring the number of inmates confined into compliance with the total design capacity.</p> <p>History Note: Authority G.S. 153A 221; Eff. June 1, 1990; Readopted Eff. September 4, 2020.</p> <p>This Rule is not met as evidenced by: Based on records review on 12/02/2025, the jail exceeded the total design capacity of the facility.</p> <p>Findings include: The male population was 58 over the male design capacity of 354, and the female population was 10 over the female design capacity of 56.</p> <p>*Non-compliance with this rule poses a significant risk, jeopardizing the safety of both detention staff and inmates. *Moreover, surpassing the designated capacity leads to violations of additional regulations, such as those governing the number of toilets, sinks, showers, and the required square footage for inmate utilization.</p>	J 21	<p>The Jail Administrator is collaborating with the local fire marshal to identify and implement a solution that will prevent the fire alarm system from displaying trouble conditions during periods of rain.</p> <p>The Jail Administrator is working with the local court system to expedite low-level cases so individuals can be moved out of the local confinement facility.</p> <p>The Jail Administrator is collaborating with surrounding counties to secure housing for inmates because of facility overcrowding.</p>	<p>02/20/26</p> <p>02/20/26</p> <p>03/01/26</p>
J 44	10A NCAC 14J .0701 Sanitation  Each jail shall comply with the North Carolina Commission for Public Health rules governing	J 44		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>110663</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/02/2025</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>ROBESON COUNTY DETENTION CENTER</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>122 LEGEND ROAD LUMBERTON, NC 28358</b>
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
J 44	<p>Continued From page 2</p> <p>sanitation as codified in Title 15A Chapter 18A Section .1500 and which are hereby adopted by reference pursuant to G.S. 150B 14(c).</p> <p>History Note: Authority G.S. 153A 221; Eff. June 1, 1990; Pursuant to G.S. 150B-21.3A, rule is necessary without substantive public interest Eff. January 5, 2016.</p> <p>This Rule is not met as evidenced by: Based on observation on the morning of 12/02/2025, the ceilings in several areas were not in compliance with the following Rule: 15A NCAC 18A .1508 WALLS AND CEILINGS (a) The walls and ceilings of all rooms and areas shall be kept clean and in good repair.</p> <p>Findings include: 1. The ceiling around the HVAC vents were extremely dirty and need to be placed on a regular maintenance schedule for proper cleaning. 2. Paint was peeling from the ceilings and walls throughout the facility. 3. Cells throughout the facility had graffiti on the walls and ceilings.</p> <p>Based on observation on the morning of 12/02/2025, the facility is not in compliance with sanitation rule 15 A NCAC 18 A .1510 TOILET, HANDWASHING AND BATHING FACILITIES: (a) Each cell shall be provided with access to toilet and handwashing facilities, and soap and individual towels shall be provided. The fixtures shall be kept clean and in good repair. (b) Each cell block or section shall be provided with bathing facilities which shall be easily cleanable and shall be kept clean.</p>	J 44	The Jail Administrator will oversee assigned crew members as they continue painting the facility.	03/01/2026

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>110663</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/02/2025</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>ROBESON COUNTY DETENTION CENTER</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>122 LEGEND ROAD LUMBERTON, NC 28358</b>
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
J 44	Continued From page 3  Findings include 1. Showers throughout the facility were dirty and had paint peeling from the walls and ceilings. 2. What appeared to be mold was on the walls in all the shower areas.	J 44	The Jail Administrator will designate staff members to ensure showers are placed on a routine spraying and cleaning schedule.	03/01/2026